



GARY R. HERBERT
Governor
SPENCER J. COX
Lieutenant Governor

State of Utah

DEPARTMENT OF NATURAL RESOURCES


MICHAEL R. STYLER
Executive Director

Division of Oil, Gas and Mining

JOHN R. BAZA
Division Director

Minerals Inspection Report

Report Date: 03/24/2015


Reviewed 

Mine Name: Sage Canyon	Permit Number: M/49/0071	Mine Status: Active
Operator Name: Geneva Rock Products	Inspection Date: 3/24/2015	Permit Fees: 1000
Inspector(s): A. Abate, P. Baker	Inspection Time: 10:00 AM	Bond Amount: \$628,000
Attendee(s): B. Sumsion	Weather: Clear, Windy 50s	Bond Escalation:
Inspection Purpose: Routine Inspection		Prior Inspection: unknown

Conclusions and Recommendations

The operator expressed interest in looking into self bonding options. In general, the plan does not need to be updated since the mining is in its early stages.

Elements of Inspection	Evaluated & Commented	Enforcement
1. <i>Permits, Revisions, Transfer, Bonds</i>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
The site is bonded for 137 acres. At the present time only 27 acres are disturbed. The operator and the Division discussed incremental bonding and explained the self-bonding option.		
2. <i>Public Safety (shafts, adits, trash, signs, highwalls)</i>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
No shafts, adits, or trash was noted on the site. The highwalls are active mining areas. The company is in the process of moving the radio and cell towers at the top of the mountain so that the area can be mined out.		
3. <i>Protection of Drainages/Erosion Control</i>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
A temporary water impoundment has been constructed. The larger 1.2 acre impoundment has not been built out to date.		
4. <i>Deleterious Material</i>	<input type="checkbox"/>	<input type="checkbox"/>
5. <i>Roads (maintenance, surfacing, dust control, safety)</i>	<input type="checkbox"/>	<input type="checkbox"/>
6. <i>Reclamation</i>	<input type="checkbox"/>	<input type="checkbox"/>
7. <i>Backfilling/Grading (trenches, pits, roads, highwalls, shafts)</i>	<input type="checkbox"/>	<input type="checkbox"/>
8. <i>Soils</i>	<input type="checkbox"/>	<input type="checkbox"/>
9. <i>Revegetation</i>	<input type="checkbox"/>	<input type="checkbox"/>
10. <i>Other</i>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
The operation is in the early stages of mining with the majority of the permitting ground still undisturbed.		

Inspector's Signature: 

CC: Brent Sumsion, bsumsion@clydeinc.com


File: /C:/Users/APRILABATE/Desktop/Inspection form 3.0.2 NewLG.pdf



Active mining area.



Topsoil Pile - only one stockpile out of the three proposed have been constructed since most of the ground is yet to be disturbed.



Temporary stormwater retention pond.